

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 23 2014

Form C-141
Revised August 8, 2011

Submit a Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Oxy Permian Ltd. 16096 Contact Chancey Summers
Address 1017 W. Stanolind Rd, Hobbs, NM 88240 Telephone No. (575) 397-8216
Facility Name Riverbend B Federal #8 SWD Battery Facility Type Battery

Surface Owner BLM Mineral Owner API No. 30-015-28390 (nearest well)

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	23	24S	29E					Eddy County, NM

Latitude N 32.20871° Longitude W 103.96273°

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 240 bbls	Volume Recovered 230 bbls
Source of Release Fatigue on a 4" poly line from the well to the battery	Date and Hour of Occurrence 06/03/2014	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD and Jennifer VanCuren, BLM	
By Whom? Kathy Purvis, BBC International	Date and Hour 06/04/2014 @ 9:40 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Fatigue on a 4" poly line from the well to the battery caused 240 bbls of produced water to leak onto the ground. A vacuum truck recovered 230 bbls of produced water and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is 20' x 50' inside the containment area. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by Environmental Specialist: 	
Title: HES Specialist	Approval Date: 6/25/14	Expiration Date: NA
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6-23-14 Phone: (575) 397-8216	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7/25/14	


* Attach Additional Sheets If Necessary

2RP-2358



Oxy

Riverbend Federal #8 SWD Battery



U/L D, Section 23, T24S, R29E
Eddy County, NM
N 32.20884° W 103.96304°
API# 30-015-28390 (nearest well)

BBC International, Inc.

Oxy

Riverbend Federal #8 SWD Battery

Date: 06/20/2014

DRWG by: K. Purvis

NOT TO SCALE

File: Oxy 2014

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Monday, June 23, 2014 4:28 PM
To: Bratcher, Mike, EMNRD; jvancure@blm.gov
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Riverbend B Federal #8 SWD Battery
Attachments: Initial C-141, Riverbend B Fed #8 SWD Btry.pdf; Site DRWG, Riverbend Fed #8 SWD Btry.docx

Attached is the initial C-141 for a leak that occurred at the Riverbend B Federal #8 SWD Battery on 06/03/2014 in Eddy County, NM. Receipt notification via email is greatly appreciated. Attached is also a site drawing. This leak stayed on location inside a lined battery.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com