

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG Operating LLC	Contact	Robert McNeil
Address	600 West Illinois Avenue, Midland, Texas 79701	Telephone No.	(432) 230-0077
Facility Name	Sly Hawk State #005	Facility Type	Main Line
Surface Owner: State	Mineral Owner	Lease No. (API#) 30-015-35103	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	03	25S	28E					

Latitude 32 09.982 Longitude 104 04.068

### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 70 bbls	Volume Recovered 0 bbls
Source of Release: Main Water Line	Date and Hour of Occurrence 09-22-2013	Date and Hour of Discovery 09-22-2013 12:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 09-25-2013 3:43 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

Describe Cause of Problem and Remedial Action Taken.\*

JUN 04 2014

Fuse failed on polyline. Fused line back together

RECEIVED

Describe Area Affected and Cleanup Action Taken.\*

Initially an estimated 70 bbls of produced water were released due to a fuse failure on a polyline. None of the fluids were recovered. The spill was on the north and south side of the road. Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 


Printed Name: Ike Tavarez (agent for COG)

Title: Project Manager

E-mail Address: Ike.Tavarez@TetraTech.com

Date: 5-28-14 Phone: (432) 682-4559

### OIL CONSERVATION DIVISION

Approved by District Supervisor: 

Approval Date: 6/23/14

Expiration Date: NA

Conditions of Approval:

Final

Attached ☐

Attach Additional Sheets If Necessary