

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

AUG 09 2012

RECEIVED

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849	Telephone No. 575-390-4186
Facility Name NEDU #247	Facility Type Injection line

Surface Owner State of NM	Mineral Owner State of NM	Lease No. 30-025-38508
---------------------------	---------------------------	------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	2	21S	37E	3465	FSL	1775	FWL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 150	Volume Recovered 55
Source of Release Injection line leak	Date 2/25/09	Date 2/25/09 3pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Natalie Gladden	Date and Hour 2/25/09 352pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

Watercourse was Impacted, Describe Fully.\*  
  
DTW = 30'

Describe Cause of Problem and Remedial Action Taken.\* Due to corrosion of 4" injection line which was buried 15' bgs blew out. This injection line ran under hwy 207 north of Eunice. The fluid was both inside and outside state fence line. No fluid was released into conduit. Line was shut in and repaired. Vac trucks recovered approx 55bbbls of pw. NM State Hwy Department was notified.

Describe Area Affected and Cleanup Action Taken.\* Due to safety hazards, the area of excavation will be dug out and backfilled at the end of each day. Proper barricades, fencing, lights and other safety measures will be taken once work begins. Contamination will be hauled to Sundance Disposal and NMOCD rules and guidelines will be followed to closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Natalie Gladden	 Approved by District Supervisor Environmental Specialist	
Title: EH&S Environmental Tech	Approval Date: 3/18/09	Expiration Date: 5/18/09
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/1/09 Phone: 575-390-4186	SUBMIT FINAL C-141 BY	IRP-09-03-2130

\* Additional Sheets If Necessary

NSAO 1417754792 