

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised August 8, 2011

MAR 27 2014
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jose A Zepeda
Address: 1410 N West County Road	Telephone No. 575-391-3165
Facility Name: Skaggs B-12	Facility Type: Battery

Surface Owner: Fed LSE# LC03-1620	Mineral Owner: N/A	API No. 30-025-20089
-----------------------------------	--------------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 12	Township 20S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Produce Water	Volume of Release: 26	Volume Recovered: 25
Source of Release: Dresser Sleeve	Date and Hour of Occurrence 03/24/14 0600	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking	
By Whom? Jose A Zepeda	Date and Hour: 03/27/2014 ~1325 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.* On Monday, 03/24/2014 @ ~0600 hrs. MST at the Skaggs B-12, an accidental discharge of ~26 BPW occurred. While checking wells, a COPC employee discovered a leak coming from a valve box at the Skaggs B-12 location. Inside the valve box, the dresser sleeve was leaking fluids. The leak was contained inside a fully contained valve box with the exception of 1 BPW over flow that spilled to ground. The well was shut in and a vacuum truck was contacted. Vacuum Truck recovered 25 BPW; NMOCD was contacted via phone call. The spill site will be remediated according to COPC and NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: JOSE A ZEPEDA	Approved by Environmental Specialist:	
Printed Name: Jose A Zepeda	Approval Date:	Expiration Date: 9-10-14
Title: LEAD HSE	Conditions of Approval: Site samples required. Delimited remediation area as per NMOCD guidelines. Submit final C-141 by 9/10/14.	
E-mail Address: Jose. A. Zepeda@conocophillips.com	Attached <input type="checkbox"/>	
Date: 03/27/2014 Phone: 575-391-3158	7-14-3146	

* Attach Additional Sheets If Necessary

JUL 09 2014 7/27

65710 217817
1701918 853894
PT01418 853698