

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 20 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address 8 Ellison Lane Eunice, NM 88231	Telephone No. (432)- 631- 6982
Facility Name Plow Boy Federal # 1	Facility Type Oil Well
Surface Owner Apache Corporation	Mineral Owner Federal
API No. 30-025-36962	

LOCATION OF RELEASE

Unit Letter J	Section 35	Township 19S	Range 38E	Feet from the 2275'	North/South Line FSL	Feet from the 2310'	East/West Line FEL	County Lea
------------------	---------------	-----------------	--------------	------------------------	-------------------------	------------------------	-----------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 21 barrels of water and 1 barrel of oil	Volume Recovered 10 barrels of water and 1/2 barrel of oil.
Source of Release pressure gauge on well head	Date and Hour of Occurrence 4/30/2014	Date and Hour of Discovery 4/30/2014 at 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking (NMOCD) and Jeffery Robertson (BLM)	
By Whom? Bruce Baker	Date and Hour 4/30/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

depth to g H₂O 50-75

Describe Cause of Problem and Remedial Action Taken.*

The pressure gauge on well head blew out resulting in the loss of fluid. The pressure gauge was isolated and a vacuum truck was dispatched to pick-up standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The affected area was all contained on the well pad. The area was mapped and field surface samples collected. The saturated soil was back dragged with a backhoe and hauled to an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Bruce Baker</i>	Approved by Environmental Specialist:	
Printed Name: Bruce Baker	Approval Date: 7-8-14	Expiration Date: 9-11-14
Title: Environmental Technician	Conditions of Approval: <i>Site Samples require</i>	
E-mail Address: larry.baker@apachecorp.com	Attached <input type="checkbox"/> 7-74-3153	
Date: 5/20/14	Phone: (432) 631-6982	

* Attach Additional Sheets If Necessary

*Deliniate remediate site as per
NMOCD guidelines. Submit Form
C-141 by 9-11-14*

*ogrid 873
N 701418 954357
P 701418*

JUL 09 2014