

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised August 8, 2011

JUL 14 2014
Submit a Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Livingston Ridge 19 Federal #1CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-35960

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	19	22S	32E					Lea County, NM

Latitude N 32.382350° Longitude W 103.72136°


NATURE OF RELEASE

Type of Release	Oil	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	External corrosion on a 2" steel production flow line	Date and Hour of Occurrence	06/23/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding, Geoffrey Leking-NMOCD; Jennifer Van Curen- BLM		
By Whom?	Kathy Purvis	Date and Hour	06/23/2014 @ 2:20 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
External corrosion on a 2" steel production flow line caused 10 bbls of oil to leak onto the ground. No fluids were recovered and the line was repaired or replaced.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 10' x 10' on and off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.


OIL CONSERVATION DIVISION

Signature:



Printed Name: Chancey Summers

Approved by Environmental Specialist:



Title: HES Specialist

Approval Date: 7-11-14

Expiration Date: 9-17-14

E-mail Address: Chancey.Summers@oxy.com

Conditions of Approval:

Attached

Date: 7-10-14 Phone: (575) 397-8216

Site Samples required.

7-14-3171

* Attach Additional Sheets If Necessary

Reimburse & remediate as per NMOCD guides. Submit final C-141 by 9-17-14

ogrid 16696
N70 1419 553950
P70 1419

JUL 14 2014