

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

Form C-141  
Revised October 10, 2003

JUL 16 2014

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy USA Inc.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Red Tank 28 Federal #3 SWD Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-31754(nearest well)

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	28	22S	32E					

Latitude N 32.36860° Longitude W 103.67844°

NATURE OF RELEASE

Depth to g (h) > 100'

Type of Release	Oil, Produced Water, and rain water	Volume of Release	50 bbls	Volume Recovered	40 bbls
Source of Release	Skimmer tank overflowed	Date and Hour of Occurrence	07/03/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding- NMOCD, Sol Hughes- BLM		
By Whom?	Jennifer Gilkey, BBC International	Date and Hour	07/11/2014 @ 3:08 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*



A skimmer tank overflowed and spilled 50 bbls of oil, produced water, and rain water onto the ground. A vacuum truck was able to recover 40 bbls of fluid.

Describe Area Affected and Cleanup Action Taken.\*

The affected area was approximately 30' x 200' on location. Remediation will be completed in accordance with a plan approved by both the NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Chancey Summers	Approved by District Supervisor:	
Title:	HES Advisor	Approval Date:	7-16-14
E-mail Address:	Chancey_Summers@oxy.com	Expiration Date:	9-19-14
Date:	7-16-14	Conditions of Approval:	Site samples required
Phone:	(575) 397-8216	Attached	<input type="checkbox"/>
		7-14-3182	

\* Attach Additional Sheets If Necessary

Delinquent and remediate as per  
NMOCD guides. Submitting final  
C-141 by 9-19-14

Grid 16696

NTO 1419 736214

P70 1419 736391

JUL 16 2014