

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company Regency Field Services, LLC	Contact Rachel Johnson	
Address P.O. Box 1226 Jal, NM 88252	Telephone No. 325-514-2636	
Facility Name Trunk M	Facility Type Natural Gas Gathering	
Surface Owner Crawford	Mineral Owner	API No. 30-025-27276

**LOCATION OF RELEASE**

Unit Letter S	Section 6	Township 25S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea County
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------------

Latitude 32.29109 Longitude -103.20259

**NATURE OF RELEASE**

Type of Release: Crude Oil, Nat. Gas and Produced Water	Volume of Release: 40bbls	Volume Recovered: 0 bbls
Source of Release 20" Natural Gas Gathering Line	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 12:00 pm on 3/27/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Email to Geoff Leking on 3/27/14 from Rachel Johnson	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Failure of a segment of twenty inch (20") pipeline resulted in the release of approximately 40 bbls of a mixture of natural gas, crude oil and produced water. Following the discovery of the release, the pipeline was fitted with a temporary pipeline clamp. Crews were able to replace 80 feet of the 20 in pipeline on 3/30/14.		
Describe Area Affected and Cleanup Action Taken.* The release affected approximately 1,500 sq. ft. of rangeland. Panther Energy will remediate in accordance with NMOCD Regulatory Guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

**OIL CONSERVATION DIVISION**

Signature: *Rachel Johnson*

Approved by Environmental Specialist:

Printed Name: Rachel Johnson

Title: EH&S Specialist

Approval Date: 8-11-14

Expiration Date: 10-13-14

E-mail Address: rachel.johnson@regencygas.com

Conditions of Approval:

*Site Samples required*

Attached ☐

Date 4/14/14

Phone: 325-514-2636 (cell)

*LRP-3228*

\* Attach Additional Sheets If Necessary

*Delivered & received 8/25/14  
NMOCD number submitted 8/25/14  
C-141 - by 10-13-14*

*ogrid 2-12-14  
N101422 338954  
P701422 339123*

AUG 11 2014