

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 11 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: David May
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3106/575-631-5907
Facility Name: MCA well #417	Facility Type: oil Well
Surface Owner: BLM	Mineral Owner BLM
API No. 3002538985	

LOCATION OF RELEASE

Unit Letter M	Section 27	Township 17S	Range 32E	Feet from the 90	North/South Line South	Feet from the 1660	East/West Line West	County LEA
------------------	---------------	-----------------	--------------	---------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.7985274628581

Longitude - 103.76068793867

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 16 BBLS	Volume Recovered: 14 BBLS
Source of Release: 3 inch Flex Line	Date and Hour of Occurrence 12/27/13 9:00 am	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos/Geoffrey Leking	
By Whom? David May	Date and Hour: 12/27/13 1:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* MSO responded to a leak on a 3 inch flex flow line for the MCA well # 417 due to a small hole in the line. MSO shut in and isolated well and submitted work order for repairs.

Describe Area Affected and Cleanup Action Taken.*

Affected area was 170 Ft X 15 Ft all on caliche pad and will be remediated according to BLM and NMOCD guidelines

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>David May</i>	OIL CONSERVATION DIVISION	
Printed Name: David May	Approved by Environmental Specialist:	
Title: LEAD HSE	Approval Date: 8-11-14	Expiration Date: 10-13-14
E-mail Address: david.d.may@conocophillips.com	Conditions of Approval: <i>Site Sample report Rebate & remediate area upon NMOCD approval</i>	Attached <input type="checkbox"/> IRP-3229
Date: 12/27/2013	Phone: 575-391-3106	

* Attach Additional Sheets If Necessary

*Submit final C-141 by
10-13-14*

*og rra 217817
ATO 1422
p701422 350 981*

AUG 12 2014