

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

AUG 12 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: David May
Address: 1410 North West County road	Telephone No. 575-391-3106
Facility Name: SEMU DTB Battery	Facility Type: Tank Battery
Surface Owner: BLM	Mineral Owner BLM
API No. 300250611500	

LOCATION OF RELEASE

Unit Letter I	Section 15	Township 20S	Range 37E	Feet from the 1980	North/South Line South	Feet from the 660	East/West Line East	County LEA
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	----------------------

Latitude **32.5712292601113**

Longitude - **103.232910645658**

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 24 BBLS	Volume Recovered: 10 BBLS
Source of Release: 4X20 Heater Treater	Date and Hour of Occurrence 11/21/13 3:00 pm	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos/Geoffrey Leking	
By Whom? David May	Date and Hour: 11/25/13 3:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


MSO found the fire tube on a heater was leaking. MSO shut in and isolated wells and called for vacuum truck. Spill amount was 10 BPW & 14 BO with 10 BO recovered.

Describe Area Affected and Cleanup Action Taken.*

Spill amount was 10 BPW & 14 BO with 10 BO recovered. Spill area was 183 Ft X 81 Ft, all on caliche pad and will be remediated according to BLM requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:		
Printed Name: David May	Approved by Environmental Specialist:	
Title: LEAD HSE	Approval Date: 8-12-14	Expiration Date: 10-14-14
E-mail Address: david.d.may@conocophillips.com	Conditions of Approval: <i>Site Supervisor required Documented & submit once as per NMOCD guidelines.</i>	Attached <input type="checkbox"/> 1RP-3233
Date: 11/22/13	Phone: 575-391-3106	

* Attach Additional Sheets If Necessary

*Submit final C-141 by
10-14-14.*

*07/14 217817
N701422 453234
P701422 453406*

AUG 13 2014