

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>ConocoPhillips</b>	Contact: <b>Jose A Zepeda</b>
Address: <b>1410 N West County Road</b>	Telephone No. <b>575-391-3165</b>
Facility Name: <b>SEMU Strawn Battery</b>	Facility Type: <b>Battery</b>

Surface Owner: Fed LSE# LC03-169A	Mineral Owner: N/A	API No. <b>30-02S-26941</b>
-----------------------------------	--------------------	-----------------------------

#### LOCATION OF RELEASE

Unit Letter <b>G</b>	Section <b>15</b>	Township <b>20S</b>	Range <b>37E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Lea</b>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE

Type of Release: <b>Produce Water</b>	Volume of Release: <b>22.90</b>	Volume Recovered: <b>20</b>
Source of Release: <b>Over flow on Tank</b>	Date and Hour of Occurrence <b>04/01/14 0355am</b>	Date and Hour of Discovery <b>SAME</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Geoffrey Leking</b>	<b>HOBBS OCD</b>
By Whom? <b>Jose A Zepeda</b>	Date and Hour: <b>04/04/14 1530</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	<b>AUG 13 2014</b>

If a Watercourse was Impacted, Describe Fully.\*

N/A

**RECEIVED**

Describe Cause of Problem and Remedial Action Taken.\* COPC employee received a high level alarm. Employee arrived on location and noticed the tank had over flowed, releasing ~ 22.90 bbls PDW to ground. COPC employee contacted a vacuum truck and notified supervisor. Vacuum truck recovered 20 bbls PDW from ground. Spill site will be remediated according to NMOCD guidelines. COPC employee submitted work order for repairs.

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature: **JOSE A ZEPEDA**

Printed Name: **Jose A Zepeda**

Title: **LEAD HSE**

E-mail Address: **Jose. A. Zepeda@conocophillips.com**

Date: **04/01/2014**

Phone: **575-391-3158**

Approved by Environmental Specialist:

Approval Date: **8-13-14**

Expiration Date: **10-15-14**

Conditions of Approval:

*Site Samples required.  
Delineate & monitor area as per  
NMOCD guidelines*

Attached ☐

**IRP-3234**

*Submit final C-141 by 10-15-14*

*09112 217812  
NTO 1422 532945  
P 70 1422 533099*

\* Attach Additional Sheets If Necessary

**AUG 13 2014**