

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD
AUG 13 2014

Form C-141
Revised October 10, 2003

RECEIVED
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GC Federal #044	Facility Type	Flowline
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-025-40237

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	20	17S	32E					Lea

Latitude 32.81492

Longitude 103.78728

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	2bbls of oil 4bbls of produced water	Volume Recovered	1bbl of oil 2bbls of produced water
Source of Release	Steel flowline	Date and Hour of Occurrence	11-10-2013	Date and Hour of Discovery	11-10-2013 2:14pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A steel flowline failed due to corrosion. Replaced the steel flowline.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 2bbls of oil and 4bbls of produced water were released from a steel flowline that developed a hole due to corrosion. We were able to recover 1bbl of oil and 2bbls of produced water with a vacuum truck. All free fluids have been removed. A work plan will be presented to the NMOCDBLM for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCDBLM rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCDBLM marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCDBLM acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:		Approved by District Supervisor:	
Printed Name:	Robert Grubbs Jr.		
Title:	Senior Environmental Coordinator	Approval Date:	8/14/14
E-mail Address:	rgrubbs@concho.com	Expiration Date:	10/16/14
Date:	11-15-2013	Phone:	432-661-6601
		Conditions of Approval:	Attached <input type="checkbox"/>
		Site Supervisor required	LRP-3240

* Attach Additional Sheets If Necessary

Delivered 2 minutes after
on NMOCDBLM grounds
Submit Form C-141 by 10/16/14

Ogrod 229137
N70 1422 631952
P70 1422 632058

AUG 14 2014