

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

AUG 20 2014 Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company CHEVRON U.S.A Inc.	Contact: Josie DeLeon	
Address 56 Texas Camp Road, Lovington, NM 88260	Telephone No. Office: 575-396-4414 ext 275 Cellular: 505-787-9816	
Facility Name Vacuum Glorietta West Unit #61	Facility Type Submersible Production Well	
Surface Owner State of New Mexico	Mineral Owner State of New Mexico	API No. 3002521432

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	36	17.0S	34.0E					Lea

Latitude 32.79698832 Longitude -103.5079993

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water Spill	Volume of Release 121.8bbls of pw & 0.45bbl of oil	Volume Recovered 60bbls
Source of Release Water Injection Station Pump	Date and Hour of Occurrence 10/16/12 8:50 PM	Date and Hour of Discovery 10/16/12 10:20 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Leking via voicemail	
By Whom? Josie DeLeon	Date and Hour 8/17/12 2:00PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Check valve failed on well head leading to release.

Describe Area Affected and Cleanup Action Taken.*

Majority of fluids stayed on the well pad with a small pasture area east of the pad impacted. On discovery vacuum truck contacted and vacuumed up the standing fluids which were sent to disposal. 60bbls of fluids recovered. Visually contaminated soil has been excavated and sent off for disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: David Pagano		Approved by Environmental Specialist:	
Title: Health & Environmental Specialist	Approval Date: 8-20-14	Expiration Date: 10-12-14	
E-mail Address: dpgn@chevron.com	Conditions of Approval: <i>Site specific report Submit final C-141 by 10-22-14</i>		Attached <input type="checkbox"/> 1RP-3264 <i>098144323</i>
Date: 10/23/12	Phone: 505-787-9816		

* Attach Additional Sheets If Necessary

AUG 21 2014

*1701423 255747
P701423 255885*