


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

n AB142-3751598

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street		Telephone No. 575-748-1471
Facility Name Bebop BPE State Com #1-H	API Number 30-015-37551	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. VO-7679
------------------------	------------------------	----------------------


LOCATION OF RELEASE

Unit Letter D	Section 36	Township 25S	Range 31E	Feet from the 660'	North/South Line North	Feet from the 330'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.09213 Longitude 103.73863

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 1750 B/PW	Volume Recovered 1700 B/PW
Source of Release Produced water flow line	Date and Hour of Occurrence 5/13/2014; 12:30 PM	Date and Hour of Discovery 5/13/2014; 12:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 5/14/2014, AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.*
The water flow line ruptured from pressure build-up, causing the release. Vacuum truck(s) were called, roustabout crew called to repair line.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 50' X 125' (north side of production pad) and an approximate area of 100' X 150' (west side of production pad). Flow line repaired. Production pad will be scraped; impacted soils will be taken to an NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the OCD. **Depth to Ground Water: >100' (approximately 325', per the ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By <u>Mike Bratcher</u> Approved by District Supervisor:	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>8/25/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: Thursday, June 05, 2014 Phone: 575-748-4217		

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
9/25/14

2RP-245A

Patterson, Heather, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Friday, August 22, 2014 3:14 PM
To: Bratcher, Mike, EMNRD
Cc: Patterson, Heather, EMNRD
Subject: C-141 (Bebop BPE State Com. #1-H)
Attachments: Bebop BPE State Com 1H 5132014.pdf

Mike,

Per our telephone conversation 8/19/2014, here is the Initial C-141 for the Bebop BPE State Com. #1, 5/13/2014 release.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
