

HOBBS OCD

AUG 27 2014

Detail:
1625 N. French Dr., Hobbs, NM 88240
Detail II:
111 S. First St., Artesia, NM 88210
Detail III:
1000 Rio Bravo Blvd., Artesia, NM 88210
Detail IV:
1120 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Minerals and Natural Resources
RECEIVED
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 10.15.30 NMAC.

GR122644 B-#7

Release Notification and Corrective Action

Name of Company	VACUUM TRUCK PREMIER	Contact	KESELL-HASSELOFF	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address	1209 S. MATHISON, LOOMIS, NM	Telephone No.	361-244-5707		
Facility Name	CRAZED/B	Facility Type	oil well		
Surface Owner		Mineral Owner		API No. 30-025-37647	

LOCATION OF RELEASE

User Letter	Section	Township	RANGE	Feet from the	North/South Line	Feet from the	East/West Line	County
	Y	Z2-5	37E	2310	FNL	2310	FEL	Lea

Latitude N 32° 24' 30" Longitude W 105° 0' 46"

NATURE OF RELEASE

Type of Release	Flow Line Blow Out	Volume of Release	10 BBL	Volume Recovered	10 BBL
Source of Release		Date and Hour of Occurrence		Date and Hour of Discovery	10-1-13 10:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	(If YES, To Whom?)			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully:

Descriptive Case of Problem and Remedial Action Taken:
**FLOW LINE RUPTURE CAUSED SPRAY AND LOSS OF 10 BBL CIRCUIT OIL.
 VACUUM TRUCK CALLED UPON DISCOVERY AND APPROXIMATE 10 BBL PRECAUT
 BACK HOE CALLED TO COVERT REMAINING SPILLAGE.
 30 X 50' AREA AT BACK OF GATHERING SITE. OIL PICKED UP AND THEN
 OVERLID GROUND WITH NEW FILL DIRT. WILL REMOVE DIRT & BRING NEW
 DIRT.**

Describe Area Affected and Cleanup Actions Taken:
**30 X 50' AREA AT BACK OF GATHERING SITE. OIL PICKED UP AND THEN
 OVERLID GROUND WITH NEW FILL DIRT. WILL REMOVE DIRT & BRING NEW
 DIRT.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCID rules and regulations all operators are required to report and file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCID marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCID acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: KESELL-HASSELOFF	Approved by Environmental Specialist:		
Title: LEASE OPERATOR	Approval Date: 8-27-14	Expiration Date: 10-28-14	
E-mail Address: PHASSELOFF@VN2LLC.COM	Conditions of Approval:	Attached: <input type="checkbox"/>	IRP 3277
Date: 10-1-13 Phone: 361-244-5707			

* Attach Additional Sheets If Necessary

Release & product area
over NOCD grounds
Soil test 8/17/14
10-28-14
Ogrod 258350
10/14/24 026230
POT 24 026603

AUG 28 2014