

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD**  
State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

SEP 02 2014  
RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: BC Federal #10	Facility Type: Flowline

Surface Owner: Federal	Mineral Owner:	API No. 30-025-37021
------------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	19	17S	32E	1650	North	1650	West	Lea

Latitude N32 48'37.76" Longitude W103 48'43.37"

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 45bbls PW	Volume Recovered: 40 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 8/15/2014 11:00 am	Date and Hour of Discovery: 8/15/2014 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding - OCD / Jeffrey Robertson - BLM	
By Whom? Amanda Trujillo	Date and Hour: 8/18/2014 5:15 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The release was caused by a crack in a PW flowline. The line was isolated and fused back together. A vacuum truck was dispatched to pick all standing fluid.

Describe Area Affected and Cleanup Action Taken.\*  
The impacted area is 425' along the road. All standing fluids were disposed of at an NMOCD approved facility. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 9-2-14	Expiration Date: 11-2-14
E-mail Address: atrujillo@concho.com	Conditions of Approval: SITE 5 apply regard Delineate & remediate area as per NMOCD guidance Submit final C-141 by 11-2-14	Attached <input type="checkbox"/> 1AP-3289 Ogrid 229137 N701424 527320 P701424 527450
Date: August 29, 2014	Phone: 575-748-6940	

\* Attach Additional Sheets If Necessary

SEP 05 2014