

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 02 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>ConocoPhillips Company</b>	Contact <b>Jesse A. Sosa</b>
Address <b>3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5</b>	Telephone No. <b>(505)391-3126</b>
Facility Name <b>Warren Unit Well #13</b>	Facility Type <b>Injection well</b>
Surface Owner <b>NMOCD</b>	Mineral Owner <b>BLM</b>
API No. <b>3002507881</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
Q	34	20S	38E	660	South	1980	East	Lea

Latitude N 32 31.4394 Longitude W 103. 08.0580

**NATURE OF RELEASE**


Type of Release <b>Produced Water</b>	Volume of Release <b>441</b>	Volume Recovered <b>21</b>
Source of Release <b>inch steel injection line</b>	Date and Hour of Occurrence <b>7/4/13 8:00am</b>	Date and Hour of Discovery <b>7/7 9am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Geoffrey Leking</b>	
By Whom? <b>Jesse Sosa</b>	Date and Hour <b>July 8, 2013 7:45 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
MSO was notified of an Injection line leaking 300 yards west of WU well #13. Employee isolated 2 inch steel line (25+ years) at the WU injection header and well.

Describe Area Affected and Cleanup Action Taken.\*  
Employee called vacuum truck and 21 BPW was recovered. Spill volume is approximately 441 BPW. Two affected areas are 64' wide X 89' long X 60" deep and 44' long X 70' wide X 36" deep. Further assessment is needed for more accurate spill volumes. NMOCD was notified and C-141 report will follow when full assessment is done.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Jesse A. Sosa</b>	Approved by Environmental Specialist: 	
Title: <b>HSER Lead</b>	Approval Date: <b>9-2-14</b>	Expiration Date: <b>11-2-14</b>
E-mail Address: <b>Jesse.A.Sosa@conocophillips.com</b>	Conditions of Approval: <i>Site Specific - give Belmonte &amp; conduct area as per NMOCD guidance.</i>	Attached <input type="checkbox"/>
Date: <b>07/18/2013</b> Phone: <b>(505)391-3126</b>		<b>IRP-2990</b>

\* Attach Additional Sheets If Necessary

*Belmonte & conduct area as per NMOCD guidance. Submit final C-141 by 11-2-14*

*oguid 217817  
NTO 1424 554451  
P 701424 554596*

SEP 05 2014