

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

**HOBBS OCD**

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 03 2014  
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: Burgundy Oil and Gas of New Mexico	Contact: Ben Taylor
Address: 401 W Texas Suite 1003 Midland, TX 79701	Telephone No. 432-684-4033
Facility Name: State Vacuum Unit #15	Facility Type: WIW

Surface Owner State	Mineral Owner State	API No. 30-025-02173
---------------------	---------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from	East/West Line	County
I	32	17S	34E	1980	South	680	East	Lea

Latitude: 32.7895034299485 Longitude -103.576372754491

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release 3bbls	Volume Recovered 3bbls
Source of Release: Flowline	Date and Hour of Occurrence 08-28-14 14:00	Date and Hour of Discovery 08-28-14 14:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD M Whitaker	
By Whom? Ben Taylor	Date and Hour: 08/28/14 14:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
NA

Describe Cause of Problem and Remedial Action Taken.\* A rupture occurred in a injection line next to the well.

Describe Area Affected and Cleanup Action Taken. Leak traversed 387 ft south of the well and ran 4ft wide in pasture area. DFSI has been retained to fully remediate the site according to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Ben Taylor	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ben Taylor	Approved by Environmental Specialist:	
Title: Field Foreman	Approval Date: 9-3-14	Expiration Date: 11-3-14
E-mail Address: btaylor.bogi@att.net	Conditions of Approval: <i>Site samples required. Delimit &amp; remediate area as per NMOCD guidelines. Submit final C-141 by 11-3-14</i>	Attached <input type="checkbox"/> IRP-3300 ogrid 2014 N701424 626337 pro17 2482 6537
Date: 08/05/14 Phone: 432-557-2684		

\* Attach Additional Sheets If Necessary

SEP 05 2014