

HOBBS OGD

SEP 03 2014

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
RECEIVED
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Devon Energy	Contact	Kenny Kidd
Address	PO Box 250, Artesia, NM 88211	Telephone No.	575-748-3371
Facility Name	Mad Dog 15 Federal Com #1	Facility Type	Oil Well

Surface Owner	Mineral Owner	API No.	30-025-36778
---------------	---------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	23S	34E	660	South	660	East	LEA

Latitude: 32.7271300239255 Longitude: 103.909386055786

NATURE OF RELEASE

Type of Release	Spill	Volume of Release	80 bbls	Volume Recovered	0
Source of Release	Water transfer line leak	Date and Hour of Occurrence	2/14/14, 8:15 AM	Date and Hour of Discovery	2/14/14, 8:15 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A water transfer line from the Mad Dog 15 Federal Com No. 1 was found to be leaking. Approximately 80 barrels of produced water was released off the east side of Adobe Road into the drainage ditch. The affected area measured approximately 3-4 feet wide by 900-feet long. No fluids were recovered. Talon/LPE was contracted to remediate this release.

Describe Area Affected and Cleanup Action Taken.* The impacted area in the drainage ditch was excavated to and depth of 3-feet deep. All of the contaminated soil was transported to Lea Land, LLC for disposal. Upon NMOCD approval of the confirmation samples the excavation was backfilled with new topsoil. The area was contoured to match the surrounding terrain. No further action is required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Handwritten Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: SANDRA D FARKY	Approved by Environmental Specialist:	
Title: Field Admin. Support	Approval Date: 9-2-2014	Expiration Date: —
E-mail Address: <i>[Handwritten Email]</i>	Conditions of Approval: —	Attached <input type="checkbox"/>
Date: 9/3/2014 Phone: 575.746.5587		IRP 5302

* Attach Additional Sheets If Necessary

SEP 05 2014

09-02-6137
N701924 649295
P701929 649401