

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 04 2014

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Apache Corp.	Contact	Natalie Gladden
Address	P.O. Box 1849, Eunice, NM, 88231	Telephone No.	(575) 390-4186
Facility Name	White Owl Battery (nearest well #1)	Facility Type	Production Facility
Surface Owner	Unknown	Mineral Owner	State of NM
		Lease No.	30-025-36689

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	2	20S	38E	582	FNL	330	FWL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil/Produced Water	Volume of Release	12 bbl	Volume Recovered	10 bbl
Source of Release	Fire Tube	Date and Hour of Occurrence	12/06/11	Date and Hour of Discovery	12/06/11
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					

Describe Cause of Problem and Remedial Action Taken.*
Southern Union's gas compressor went down overnight and the heater treater pressured up resulting in a failure of the fire tube gasket. Spray area was back-dragged immediately. Most of the fluid remained inside the bermed area, but did spray the pasture area.

Describe Area Affected and Cleanup Action Taken.*
The leak affected the bermed containment and an area to the south of the berm, including overspray into pasture land. Impacted soils were removed to a NMOCD approved disposal facility. Representative soil samples were collected from the excavations and sent to a commercial laboratory for chloride and TPH confirmation. The excavations were backfilled with clean soils and leveled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name:	Natalie Gladden	Approved by District Supervisor: <i>Sumale Spoonline</i>	
Title:	EH&S Environmental Tech	Approval Date:	9-4-14
E-mail Address:	Natalie.gladden@apachecorp.com	Expiration Date:	_____
Date:	11/9/14	Conditions of Approval:	_____
Phone:	(575) 390-4186	Attached	<input type="checkbox"/>

IRP-3306
n70 1429654460
p70 1424654600

SEP 05 2014

* Attach Additional Sheets If Necessary