


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*NA B1425242214*

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Myox 21 SWD #1	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-22434
----------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	21	25S	28E	1980	North	660	West	Eddy

Latitude: 32.11699 Longitude: 104.09894

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 80 bbls	Volume Recovered: 30 bbls
Source of Release: Wellhead	Date and Hour of Occurrence: 8/14/2014 7:00 am	Date and Hour of Discovery: 8/14/2014 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Amanda Trujillo	Date and Hour: 8/15/2014 4:33 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The needle valve atop the pumping-T sheared off releasing water onto the ground. Repairs were made to wellhead and a vacuum truck was dispatched to pick up any standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area is 300' x 200' to the north of the wellhead. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>Mike Bratcher</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>9/9/14</i>	Expiration Date:
E-mail Address: <i>atrujillo@concho.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines.	
Date: August 28, 2014 Phone: 575-748-6940	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN:** *10/14/14*

*2BP-2475*

**Bratcher, Mike, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Thursday, August 28, 2014 5:38 PM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** (C-141) Myox 21 SWD #1 (30-015-22434)  
**Attachments:** 08-14-2014 Myox 21 SWD #1 (WH) Inital.pdf

Mr. Bratcher,

Attached is a C-141 for your consideration. Please feel free to contact me if you have any additional questions or concerns.

Thank you,

**Amanda Trujillo**

Senior Environmental Coordinator  
COG Operating LLC  
Cell: 505.350.1336  
Office: 575.748.6930  
[atrujillo@concho.com](mailto:atrujillo@concho.com)

2208 W. Main St.  
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

---

**From:** Amanda Trujillo  
**Sent:** Friday, August 15, 2014 4:33 PM  
**To:** 'Bratcher, Mike, EMNRD'  
**Cc:** HSE-Environmental; Production Mail  
**Subject:** (Notification) Myox 21 SWD #1 (30-015-22434)

Mr. Bratcher,

COG Operating LLC is reporting a release at the **Myox 21 SWD #1 (30-015-22434)**.  
The release occurred at 7:00 am on 08/14/2014.

**Released:** 80 bbls PW

**Recovered:** 30 bbls PW

This release was caused by corrosion of a needle valve atop the pumping T. The site is being evaluated for clean-up and a C-141 submitted. If you have any additional questions please feel free to contact me.

Thank you,

**Amanda Trujillo**

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

[atrujillo@concho.com](mailto:atrujillo@concho.com)

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

## Bratcher, Mike, EMNRD

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Friday, August 15, 2014 4:33 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** HSE-Environmental; Production Mail  
**Subject:** (Notification) Myox 21 SWD #1 (30-015-22434)

Mr. Bratcher,

COG Operating LLC is reporting a release at the **Myox 21 SWD #1 (30-015-22434)**.

The release occurred at 7:00 am on 08/14/2014.

**Released:** 80 bbls PW

**Recovered:** 30 bbls PW

This release was caused by corrosion of a needle valve atop the pumping T. The site is being evaluated for clean-up and a C-141 submitted. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

[atrujillo@concho.com](mailto:atrujillo@concho.com)

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.