

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

HOBBS OCD

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 26 2014

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company	COG Operating LLC	Contact	Robert McNeil
Address	600 West Illinois Avenue, Midland, Texas 79701	Telephone No.	(432) 230-0077
Facility Name	Pronghorn SWD #1	Facility Type	Central Booster Station
Surface Owner: Federal	Mineral Owner	Lease No. (API#)	30-025-32735

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	24	19S	32E	330	North	1650	East	Lea

Latitude N 32.65220 ° Longitude W 103.71675°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 1500 bbls	Volume Recovered 1300 bbls
Source of Release 1x4 swedge	Date and Hour of Occurrence 11/20/09	Date and Hour of Discovery 11/20/09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Paul Evans - BLM, Maxey Brown - OCD	
By Whom?	Date and Hour 11/20/09 3:38 pm, 4:37 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A 1x4 swedge broke off the discharge of the pump going to the Pronghorn well. Replaced with a heavy duty metal swedge.		
Describe Area Affected and Cleanup Action Taken.* About 25% of the battery pad was covered with produced water. The majority of the produced water went off the location south of the battery into the pasture. Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez	Approved by District Supervisor: 	
Title: Senior Project Manager, P.G.	Approval Date: 9-26-14	Expiration Date: —
E-mail Address: ike.tavarez@tetratech.com	Conditions of Approval: —	Attached <input type="checkbox"/>
Date: 9/16/14 Phone: (432) 682-4559	1RP-3339	

\* Attach Additional Sheets If Necessary

SEP 26 2014

Sign 229132  
2701426 943423  
2701426 943859

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

SEP 26 2014

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 100 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name - Pronghorn SWD #1	Facility Type- Central booster station		
Surface Owner	Federal	Mineral Owner	
		Lease No.	30-025-32735

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	24	19S	32E	330	North	1650	East	Lea

Latitude 32.65220 Longitude 103.71675

## NATURE OF RELEASE

Type of Release- Produced water	Volume of Release-1500 bbls	Volume Recovered- 1300 bbls
Source of Release- 1x4 swedge	Date and Hour of Occurrence- 11/20/09 AM	Date and Hour of Discovery 11/20/09 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Paul Evans/ BLM, Maxey Brown/ OCD	
By Whom? Pat Ellis, Kanicia Castillo	Date and Hour 11/20/09 3:38pm, 4:37pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A 1x4 swedge broke off the discharge of the pump going to the Pronghorn well. Replaced with a heavy duty metal swedge.

Describe Area Affected and Cleanup Action Taken.\*

About 25% of the battery pad was covered with produced water. The majority of the produced water went off location south of the battery into the pasture. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:	
Printed Name: Kanicia Carrillo	<i>Kanicia Carrillo</i>	
Title: Regulatory Analyst	Approval Date: <u>9-25-14</u>	Expiration Date: <u>      </u>
E-mail Address: <u>kcarrillo@conchoresources.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>11/25/09</u> Phone: <u>432-685-4332</u>	<u>Site Spill repair</u>	<u>IRP-3359</u>

\* Attach Additional Sheets If Necessary

*Revised 8/1/14*  
*as per NMOCD guidelines.*

*Original 229137*  
*11/20/14 26 943423*  
*11/20/14 26 943859*