

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

OCT 23 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <i>Finley Resources Inc.</i>	Contact <i>Raymond Dodd</i>	
Address <i>1308 Lake St. Ft. Worth, Tx. 76102</i>	Telephone No. <i>432-202-8269</i>	
Facility Name <i>South Texas Fed.</i>	Facility Type <i>Tank Battery - Production</i>	
Surface Owner <i>(H)</i>	Mineral Owner	API No. <i>30-025-27748</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>G</i>	<i>23</i>	<i>20S</i>	<i>33E</i>	<i>1980</i>	<i>N</i>	<i>2310</i>	<i>E</i>	<i>Lea</i>

Latitude *32.560226* Longitude *-103.633156*

NATURE OF RELEASE

Type of Release <i>Oil</i>	Volume of Release <i>35 Bbls</i>	Volume Recovered <i>30 Bbls.</i>
Source of Release <i>Prod. Tank Overflow</i>	Date and Hour of Occurrence <i>10/20</i>	Date and Hour of Discovery <i>10/21</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Tommy Oberding OCD</i>	
By Whom? <i>Raymond Dodd</i>	Date and Hour <i>10-21 8:00 AM</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>NA</i>	

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.* *all oil contained within Berm was picked up & put back into tanks*

Production Equip. malfunction - water leg on heater treater plugged, putting water in oil tank causing spill

Describe Area Affected and Cleanup Action Taken.* *Clean up to be performed by approved environmental comp.*

all oil spilled was contained within Berm & was picked up by vac truck

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed Name: <i>Raymond Dodd</i>		Approved by Environmental Specialist:	
Title: <i>Prod. Supt.</i>		Approval Date: <i>10-24-14</i>	Expiration Date: <i>12-24-14</i>
E-mail Address: <i>rdodd@finleyresources.com</i>	Conditions of Approval: <i>Site Supervisor Delante & - ducto area open NMOCD approved. Subrio final C-141 by 12-24-14</i>	Attached <input type="checkbox"/> <i>IRP 3393</i>	
Date: <i>10-23-14</i>	Phone: <i>432-202-8269</i>		

* Attach Additional Sheets if Necessary

OCT 27 2014