

HOBBS OGD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
RECEIVED
South St. Francis Dr.
Santa Fe, NM 87505

Form C-14
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Regency Field Services LLC.	Contact: Crystal Callaway
Address: 301 Commerce Street, Suite 700, Fort Worth, TX 76102	Telephone No.: (817) 302-9407
Facility Name: Lea County Field	Facility Type: Natural Gas Gathering
Surface Owner: Elena Bell Grobe	Mineral Owner: Fee
API No.: 30-025-1106P WTR90	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	8	24S	37E					Lea

Latitude 32.235700 Longitude -103.177766

NATURE OF RELEASE

Type of Release: Crude Oil and Natural Gas	Volume of Release: 36 bbls Crude Oil and 50 mcf Natural Gas	Volume Recovered: None
Source of Release: 4" Natural Gas Pipeline	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 08/26/2008 9:10 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Buddy Hill NMOCD	
By Whom?	Date and Hour: 08/26/2008 9:12 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 4" Natural gas pipeline leaked releasing natural gas and crude oil. The line was blocked in and blown down. Permanent repairs will be made by replacing approximately 500 ft. Of 4" steel line with 4" Poly pipe.

Describe Area Affected and Cleanup Action Taken.*

The area affected measured approximately one hundred sixty (160) feet in length and varied from approximately thirty five (35) feet to sixty (60) feet in width, and was approximately nineteen (19) feet in depth. The impacted soil was removed, stockpiled onsite and remediated by mixing and blending methods. Confirmation samples were collected from the excavation floor, side walls and stockpiles. The samples were sent to an NMOCD approved laboratory, which determined concentrations of BTEX and TPH were within the regulatory standards. The NMOCD granted verbal approval to leave elevated chloride concentrations in-situ and remediate at the time of abandonment. The site was backfilled with the remediated stockpiles and the surface was restored.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Crystal Callaway</i>	OIL CONSERVATION DIVISION	
Printed Name: Crystal Callaway	Approved by Environmental Specialist:	
Title: Sr. Environ. Remediation Spec	Approval Date: 10-24-14	Expiration Date: _____
E-mail Address: Crystal.Callaway@regency.com	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: 10/24/14	Phone: 817-302-6514	IRP-1440

OCT 27 2014