

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD** State of New Mexico  
Energy Minerals and Natural Resources  
**OCT 29 2014**  
Oil Conservation Division  
1220 South St. Francis Dr.  
**RECEIVED** Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address 8 Ellison Lane Eunice, NM 88231	Telephone No. 432-631-6982
Facility Name WBDU # 38	Facility Type injection well

Surface Owner Millard Deck Estates	Mineral Owner Federal	API No. 30-025-09906
------------------------------------	-----------------------	----------------------

### LOCATION OF RELEASE

Unit Letter O	Section 9	Township 21S	Range 37E	Feet from the 660'	North/South Line FSL	Feet from the 1980'	East/West Line FEL	County Lea
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	------------------------	-----------------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 Barrels of water	Volume Recovered 1 Barrel of water
Source of Release injection line	Date and Hour of Occurrence 3/27/14	Date and Hour of Discovery 3/27/14 at 6:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The release occurred below isolation valve coupling. The well was shut in and a vacuum truck was dispatched to pick-up standing fluid. The valve was replaced.

Describe Area Affected and Cleanup Action Taken.\* The release was 7,931 square feet with approximately 4,000 square feet in the pasture. A vacuum truck was dispatched and recovered 1 barrel of fluid. The area was mapped and field surface samples collected.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bruce Baker</u>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bruce Baker		Approved by Environmental Specialist:	
Title: Environmental Technician		Approval Date: <u>10-29-14</u>	Expiration Date: <u>12-29-14</u>
E-mail Address: <u>larry.baker@apachecorp.com</u>		Conditions of Approval: <u>Site sample report.</u> <u>Releases &amp; remediate area as per</u> <u>NMOCD guides</u>	Attached <input type="checkbox"/> <u>IRP 3378</u>
Date: <u>4/17/14</u>	Phone: <u>(432) 631-6982</u>		

\* Attach Additional Sheets If Necessary

6974 873  
NTD 14 30 248958  
PTD 14 30 24 9116

**OCT 30 2014**