

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: David May	
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3106	
Facility Name: Ruby Federal Well #9	Facility Type: Well	
Surface Owner: BLM	Mineral Owner BLM	API No. 3002540360

LOCATION OF RELEASE

Unit Letter O	Section 18	Township 17S	Range 32E	Feet from the 480	North/South Line South	Feet from the 1650	East/West Line East	County LEA
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude **32.8286948558908**

Longitude **-103.802651025065**

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 51 BBLs	Volume Recovered: 30 BBLs
Source of Release: 1/4 inch Gauge	Date and Hour of Occurrence 11/11/13 8:00 am	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos/Geoffrey Leking	
By Whom? David May	Date and Hour: 11/12/13 3:50 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

At the Ruby Federal #9 the top of a 1/4 inch gauge had blown out. Spill amount was 36 BPW and 15 BO with 20 BPW and 10 BO recovered. MSO blocked in 1/4 inch valve, removed handle and replaced gauge.

Describe Area Affected and Cleanup Action Taken.*

Effectuated area was 81 Ft X 141 Ft. and will be remediated according to BLM requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: David May		Approved by Environmental Specialist:	
Title: LEAD HSE		Approval Date: 10-31-14	Expiration Date: 12-31-14
E-mail Address: david.d.may@conocophillips.com		Conditions of Approval: <i>Site specific response developed, include area per NMOCD guidance.</i>	Attached <input type="checkbox"/> IRP-3402
Date: 11/12/13	Phone: 575-391-3106		

* Attach Additional Sheets If Necessary

Ogrod: 217817
into 1930450720
P70 1430 450936

OCT 31 2014