

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

OCT 29 2014

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

RECEIVED

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <u>Tandem Energy Corp.</u>	Contact: <u>Ernie Sanchez</u>
Address: <u>2700 Fort Drake Blvd Suite 1000 Houston TX</u>	Telephone No.: <u>575-703-6865</u>
Facility Name: <u>Pure Skel Btry</u> <u>77054</u>	Facility Type: <u>Fluid transfer flow line</u>
Surface Owner	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<u>34</u>	<u>19S</u>	<u>34E</u>					<u>Lee</u>

Latitude 32.609337 Longitude -103.512683

NATURE OF RELEASE

Type of Release: <u>Flowline leak</u>	Volume of Release: <u>12 bbls</u>	Volume Recovered: <u>none</u>
Source of Release: <u>hole in flowline fluid spraying out</u>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Communicate with Tomas Oberding NMCD</u>	
By Whom? <u>Tomas Oberding</u>	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <u>Depth to ground H₂O 8'100'</u>	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Hole in poly pipe (transfer line) talk with Tomas (OCD) Oberding & Jeff Robinson (BLM) Set one cell 811, Cell Contract Alfredo Trucking. Haul Contamination to R360 approved waste site.

Describe Area Affected and Cleanup Action Taken.* Area on fence line state land on North fence. Federal land on south side of fence where fluid is. BLM said not to do anything yet. get with Tomas - come in from North side, do minimum excavation 4' depth at the next cap with valve then top soil & reseed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Ernest Sanchez</u>	Approved by Environmental Specialist:	
Printed Name: <u>Ernest Sanchez</u>	Approval Date:	Expiration Date:
Title: <u>West Texas/Eastern New Mexico Superintend</u>	Conditions of Approval:	
E-mail Address: <u>esanchez@platenergy.com</u>	Attached <input type="checkbox"/>	
Date: <u>10-27-14</u> Phone: <u>575-703-6865</u>	<u>For Record</u> <u>1RP-3397</u>	

* Attach Additional Sheets If Necessary

only

Ogird 236193
701430454461
P701430454695
F701430454302

OCT 31 2014