

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Southern Union Gas Services, Ltd.	Contact	Tony Savoie
Address	P.O. Box 1226 Jal, N.M. 88252	Telephone No.	505-395-2116
Facility Name	Lea County Field Dept.	Facility Type	Natural Gas Gathering

Surface Owner: Jarold and Dan Doom	Mineral Owner: State	Lease No.
------------------------------------	----------------------	-----------

LOCATION OF RELEASE

Unit Letter P	Section 5	Township 24S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude N32 14.491 Longitude W103 10.858

NATURE OF RELEASE

Type of Release : Crude Oil, and Natural Gas	Volume of Release: Greater than 50 mcf gas and 10 bbls crude oil	Volume Recovered	NONE
Source of Release : 10" Natural Gas Pipeline	Date and Hour of Occurrence not known	Date and Hour of Discovery	6/4/09 10:23 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?		
By Whom?	Date and Hour:		
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.		

a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.*

The 10" Natural gas pipeline developed a leak while operating at approximately 30 psi, the affected area was clamped, all of the crude oil that was released had soaked into the ground. Permanent repairs were made the following day.

Describe Area Affected and Cleanup Action Taken. Approximately 1950 sq. ft. of pasture land was affected by the leak and temporary repair. Final remediation will follow the NMOCD recommended guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name:

Title:

E-mail Address:

Date: 7/31/09

Phone: 505-395-2116

Approved by District Supervisor:

Approval Date: 11-03-14

Expiration Date: 1-03-15

Conditions of Approval:

Attached ☐

Sgt. Supler

IRP-2899

* Attach Additional Sheets If Necessary

21214
F701430749772
N701430749936
P701430750090

NOV 04 2014