

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD

NOV 04 2014

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Merle Lewis
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-748-6304
Facility Name	Thistle Unit 6	Facility Type	Gas

Surface Owner	State	Mineral Owner	State	API No.	30-025-34767
---------------	-------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	34	23S	33E	660	South	1560	East	Lea

Latitude: 32.255572574

Longitude: 103.556178132

NATURE OF RELEASE

Type of Release	Drilling Mud and Unknown fluid	Volume of Release	5bbls	Volume Recovered	0bbls
Source of Release	Illegal Dump from unknown party	Date and Hour of Occurrence	11-1-2014 9:45 pm	Date and Hour of Discovery	11-1-2014 9:45 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding; OCD		
By Whom?	Matt Nettles	Date and Hour	11-3-2014 11:30 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Illegal dump from unknown party on Devon location. Material dumped was determined to be a combination of drilling mud mixed with an unknown fluid. The unknown material is located 30ft to the Northwest of the wellhead.

Describe Area Affected and Cleanup Action Taken.*

Drilling mud mixed with unknown fluid was illegally dumped on well location. Contents of dump is only on the caliche well pad. Talon has been contacted and will determine what actions need to be taken in order to satisfy appropriate agencies.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Corina Moya	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 11-3-14	Expiration Date: 1-4-15
E-mail Address: corina.moya@dmv.com	Conditions of Approval: Site Sample report. Relocate evidence area per NMOCD guide	Attached <input type="checkbox"/>
Date: 11-4-2014 Phone: 575.746.5559	Submit Final C-141 by 1-4-15	IRP-7410

* Attach Additional Sheets If Necessary

NOV 10 2014