

District I
1225 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 N. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jose A Zepeda
Address: 1410 N West County Road	Telephone No. 575-391-3165
Facility Name: BMT Battery	Facility Type: Battery
Surface Owner: Federal Lsc # LC031695B	Mineral Owner: API No.

LOCATION OF RELEASE

Unit Letter N	Section 20	Township 20S	Range 38E	Feet from the 	North/South Line 	Feet from the 	East/West Line 	County Lea
-------------------------	----------------------	------------------------	---------------------	--------------------------	-----------------------------	--------------------------	---------------------------	---------------

Latitude Longitude

NATURE OF RELEASE

Type of Release: OIL	Volume of Release: 6.16 BBL	Volume Recovered: 3 BBL
Source of Release: Cracked weld on circulation line	Date and Hour of Occurrence 02/12/14 1040am	Date and Hour of Discovery 02/09/14 0807am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking	
By Whom? Jose A Zepeda	Date and Hour: 02/12/14 1040am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.* On 02/09/14 @ ~ 0807 am @ the BMT Battery there was an accidental discharge. COPC MSO received a call that he had a leak at the BMT Battery. COPC MSO arrived at location and notices that the leak was coming from a cracked weld on the circulation line. The leak appeared to be due to internal corrosion. COPC MSO shut in line. Spill site area was 10' wide by 170' long and 2" deep and 3bbls were recovered. Spill site will be remediated according to NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: JOSE A ZEPEDA	Approved by Environmental Specialist:	
Printed Name: Jose A Zepeda	Approval Date: 1-5-15 Expiration Date: 1-5-15	
Title: LEAD HSE	Conditions of Approval: Site Sample report Delivered & results met per NMOCD guidelines. Subic	Attached <input type="checkbox"/> IRP-3711
E-mail Address: Jose. A. Zepeda@conocophillips.com	Date: 02/12/2014 Phone: 575-391-3158	

* Attach Additional Sheets If Necessary

File C-141 by 1-5-15

F7D 1431046509
Ogwin 217817
N701431046560
P701431046858

NOV 10 2014