

HOBBS OCD

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Minerals and Natural Resources  
Oil Conservation Division  
220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report


Name of Company	Linn Operating Inc.	Contact	E.L. Gonzales
Address	2130 W Bender Blvd Hobbs, NM 88240	Telephone No.	575-738-1739
Facility Name	Topaz 19 Fed Com #1	Facility Type	Gas well
Surface Owner	Federal	Mineral Owner	
		API No. 30-025-22564	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	19	20S	34E	660	South	2084	West	LEA

Latitude 32.5531652922566 Longitude -103.601390977587

### NATURE OF RELEASE

Type of Release	Produced Water / Condensate	Volume of Release	10 bbls / 25bbls	Volume Recovered	0 / 20 bbls
Source of Release	1 inch pipe	Date and Hour of Occurrence	11/10/2014	Date and Hour of Discovery	11/11/2014 12:02 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding - NM OCD James Amos-BLM			
By Whom?	Bob Akin	Date and Hour 11/11/2014			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* upon arrival at location. I noticed that fluid was in the dike, due to a 1 inch line on the back of the tank that had fallen off due to corrosion.					
Describe Area Affected and Cleanup Action Taken.* Fluid contained on location in the dike.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: E.L. Gonzales		Approved by Environmental Specialist:			
Title: Production Supervisor		Approval Date: 11-12-14		Expiration Date: 1-12-15	
E-mail Address: elgonzales@linenergy.com		Conditions of Approval: Site Supervisor Deliver & install new upon NMOCD guide - Subir Rude C-141 by 1-12-14		Attached <input type="checkbox"/> IRP-3419 269324 2014 3163 0731 2014 3163 1108	
Date: 11/11/2014 Phone: 505-504-8002					

\* Attach Additional Sheets If Necessary

NOV 14 2014