

HOBBS OGD

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Minerals and Natural Resources  
Oil Conservation Division  
RECEIVED NOV 12 2014  
220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company – EOG Resources, Inc.	Contact – Ryan Kainer
Address – 5509 Champions Drive, Midland, TX 79706	Telephone No. (432) 686-3662
Facility Name – Falcon 25 FED 1H	Facility Type – Oil Well

Surface Owner – BLM	Mineral Owner – New Mexico	API No. 30-025-39560
---------------------	----------------------------	----------------------

### LOCATION OF RELEASE

Unit Letter C	Section 25	Township T24S	Range R33E	Feet from the 330	North/South Line S	Feet from the 2210	East/West Line West	County Lea
------------------	---------------	------------------	---------------	----------------------	-----------------------	-----------------------	------------------------	---------------

Latitude 32.1949 Longitude -103.5274

### NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release - 720 bbls	Volume Recovered – 670 bbls
Source of Release – Flare leaked oil on location	Date and Hour of Occurrence: 5/8/2014, 6:00 PM	Date and Hour of Discovery 5/8/2014

Was Immediate Notice Given?  
☒ Yes ☐ No ☐ Not Required

If YES, To Whom?  
Geoffery Leking (NMOCD)

By Whom? Ryan Kainer

Date and Hour 5/10/2014

Was a Watercourse Reached?  
☐ Yes ☒ No

If YES, Volume Impacting the Watercourse.

If a Watercourse was Impacted, Describe Fully.\*

NA

Describe Cause of Problem and Remedial Action Taken.\*


A poly line leak released approximately 720 bbls of produced water into containment and flowed off location. Approximately 670 bbls were recovered.

Poly line was repaired. A sampling plan and remediation of the spill will be underway pending approval.

Describe Area Affected and Cleanup Action Taken.\*

The spill area will be sampled and analyzed for Chlorides and Total Petroleum Hydrocarbons. The impacted area will be excavated, stockpiled on poly-plastic, and transported to an approve disposal facility. Clean material will be backfilled within the excavated area to normal grade.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ryan Kainer	Approved by Environmental Specialist:	
Title: Sr. Safety & Environmental Rep.	Approval Date: 11-12-14	Expiration Date: 1-12-15
E-mail Address: ryan_kainer@eogresources.com	Conditions of Approval: Site specific report Revised & radonius rule upon NMOCD guide - Submit final 6-14-14 1-12-15	Attached <input type="checkbox"/>
Date: 5/12/2014 Phone: 432-686-3662		IRP-7424 ogid 7377 1701731647649

\* Attach Additional Sheets If Necessary

NOV 14 2014