<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

Date: 11/07/2014

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

NOV 1 4 20 Qil Conservation Division 1220 South St. Francis Dr. Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 - Release Notification and Corrective Action **OPERATOR** Initial Report Final Report Name of Company: Conoco Phillips Company Contact: Dennis Martinez Address: 3300 N. A St. Midland, TX Telephone No.: 432-741-1818 Facility Name: H&P Rig 486 Facility Type: Drilling Rig API No. 30-025-41706 Surface Owner Mineral Owner LOCATION OF RELEASE Unit Letter Feet from the North/South Line Feet from the East/West Line Section Township Range County R32E 16block T26S Lea Lea County, New Mexico Section 16 Block T26S R32E Latitude : 32 02' 57.40N" Longitude : 103 40' 18.97" **NATURE OF RELEASE** Volume of Release: 15 bbl Volume Recovered: 14bbl Type of Release: Spill to ground Date and Hour of Occurrence Source of Release: Frac Pit Date and Hour of Discovery If YES, To Whom? 11/5/2014 @2230 hrs. 11/5/2014 @2235hrs. Was Immediate Notice Given? Date and Hour: 11/06/2014 @0930 hrs By Whom? Tommy Turner If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully,* None Describe Cause of Problem and Remedial Action Taken.* On Tuesday, November 05, 2014 at approximately 2230 hrs. while transferring drilling mud from the rigs active pit system to storage frac tank, the frac tank was over filled causing approximately 15 bbl of drilling mud (Brine Water) to spill onto the ground. Pumping was stopped and remediation began immediately. Describe Area Affected and Cleanup Action Taken.* The area affected was just off the caliche drilling pad where a small stream of fluid flowed. Roustabout company was dispatched to location with a loader to pick up soiled area which was hauled off to disposal site. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Dennis R. Martinez Approved by Environmental Specialist: Printed Name: Dennis R. Martinez Title: Well Site Safety Rep Expiration Date: /~/4-/5 Approval Date: //- /4 -/4 Delute 2, mlate and par 1RP 3424

Nono CO grade. Safar Fun 09 in 2178/2

C-141 by 1-14-15

NOV 1 4 2011 p-10/4 31 83 1724 E-mail Address: Dennis.R.Martinez@contractor.conocophillips.com

Phone: 432-688-9012