

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

NOV 14 2014
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED
Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Cimarex Energy	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Bondurant 10 SWD	Facility Type SWD

Surface Owner	Mineral Owner	API No. 30-025-32431
---------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 01	Township 19S	Range 32E	Feet from the 990	North/South Line N	Feet from the 1980	East/West Line E	County Lea
------------------	---------------	-----------------	--------------	----------------------	-----------------------	-----------------------	---------------------	---------------

Latitude 32.6938 Longitude -103.71766

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 40 bbls	Volume Recovered 15 bbls
Source of Release load line	Date and Hour of Occurrence 11/11/2014	Date and Hour of Discovery 11/11/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Doc Oberding	
By Whom? Gloria Garza	Date and Hour 11/12/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A Basic Water hauler was filling his truck from the load line and inadvertently left the valve partially open.

Describe Area Affected and Cleanup Action Taken.*

Basic has contacted SESI in Hobbs to remediate the impacted soils.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Christine Alderman</i>	Approved by Environmental Specialist:	
Printed Name: Christine Alderman		
Title: ESH Supervisor	Approval Date: 11-14-14	Expiration Date: 1-14-15
E-mail Address: calderman@cimarex.com	Conditions of Approval: <i>5th Super repair</i> <i>Robert R. ...</i>	Attached <input type="checkbox"/> <i>IRP-3425</i>
Date: Phone: 432-853-7059		

* Attach Additional Sheets If Necessary

NMOCD genda - Submitted
C-141 by 1-14-15

162683
11/14 3185 3076
11/14 3185 3231

NOV 14 2014