

DEC 01 2014

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit a Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NABK33649200*

**OPERATOR**

Initial Report  Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471	
Facility Name Cutter APC #2H	Facility Type	

Surface Owner Fee	Mineral Owner Fee	API No. 30-015-41786
----------------------	----------------------	-------------------------

**LOCATION OF RELEASE**

Unit Letter M	Section 21	Township 19S	Range 25E	Feet from the 551	North/South Line South	Feet from the 95	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	---------------------	------------------------	----------------

Latitude 32.64054 Longitude 104.49753

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 20 B/PW	Volume Recovered 18 B/PW
Source of Release Poly line	Date and Hour of Occurrence 11/21/2014; AM	Date and Hour of Discovery 11/21/2014; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The poly line busted, causing the release. Vacuum truck(s) and roustabout crew was called.

Describe Area Affected and Cleanup Action Taken.\*  
An approximate area of 10' X 10' around tin horns near a battery. The poly line was replaced and the vacuum truck removed standing fluid (18 B/PW). Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: 50-99' (approximately 50-75', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amber Cannon</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amber Cannon	Signed By <i>Mike Bernier</i> Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Agent	Approval Date: <u>12/2/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: ACannon@yatespetroleum.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/>	
Date: December 1, 2014	Phone: 575-748-4111	

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO**  
**LATER THAN: 11/21/15**

*2RP-263A*

## Bratcher, Mike, EMNRD

---

**From:** Tanna Adams <TCAAdams@yatespetroleum.com>  
**Sent:** Monday, December 01, 2014 3:42 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Amber Cannon; Bob Asher; Patterson, Heather, EMNRD  
**Subject:** Cutter APC #2H  
**Attachments:** Cutter APC #2H.pdf

Mr. Bratcher,

Please find attached the C141 Initial for the below listed location:

**Cutter APC #2H**  
**30-015-41786**  
**Section 21, T19S-R25E**  
**551 FSL & 95 FWL**  
**Eddy County, New Mexico**

Thank you,

*Tanna Adams*  
Yates Petroleum Corporation  
Environmental Tech  
Environmental Department  
[TCAAdams@yatespetroleum.com](mailto:TCAAdams@yatespetroleum.com)

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

---