

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DEC 01 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1433652494

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Owl 20504 JV-P #5 SWD	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-34749
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	18	26S	27E	1980	South	2080	West	Eddy

Latitude 32.040589764512 Longitude -104.231120202515

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 62 bbls PW	Volume Recovered: 60 bbls PW
Source of Release: Broken fitting	Date and Hour of Occurrence: 11/13/2014 2:13pm	Date and Hour of Discovery: 11/13/2014 2:13pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a broken fitting on piping within the battery. Repairs were made and vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. All recovered fluids were disposed of at an NMOCD approved facility and the battery was put back into production.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>Mike Burrows</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>12/2/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: December 1, 2014 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2BR-2637

Bratcher, Mike, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Monday, December 01, 2014 4:34 PM
To: Bratcher, Mike, EMNRD; james_amos@blm.gov
Subject: (Notification-C-141 Initial Final) Owl 205204 JV-P #5 (30-015-34749)
Attachments: 11-13-2014 Owl 20504 JV-P #5 SWD (TB) I-F.pdf

Mr. Bratcher/Mr. Amos,

COG Operating LLC is reporting a release on the Owl 205204 JV-P #5 (30-015-34749).

Unit K, Section 18 Township 26S Range 27E

The release occurred at 2:13 pm on 11/13/2014.

Released: 62 bbls Oil

Recovered: 60 bbls Oil

The release was due to a broken fitting on piping within the battery with all fluid contained within the lined facility. I apologize for the lateness of this report. We have experience problems with our new electronic reporting. We are working to correct the problems. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2407 Pecos Ave.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review,