


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company	Judah Oil, LLC	Contact	James B. Campanella
Address	PO Box 568, Artesia, NM 88211	Telephone No.	575-746-1280
Facility Name	Oxy T-Bone Federal #1	Facility Type	Salt Water Disposal
Surface Owner.	BLM	Mineral Owner	BLM
		API No.	30-015-32122

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	33	18S	31 E	660	North Line	1980	West Line	Eddy Co., NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE

Type of Release	Oil & BS	Volume of Release	180 bbls	Volume Recovered	170 bbls
Source of Release	Gun Barrel	Date and Hour of Occurrence	2/5/2013 8:00 PM	Date and Hour of Discovery	2/5/2013 9:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher NMOC D Dist 2 office		
By Whom?	James B. Campanella	Date and Hour	2/6/2013 8:00 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Valve was closed during equipment repair and wasn't re-opened.

Describe Area Affected and Cleanup Action Taken.\*  
All liquids were contained in fire wall. The fire wall is lined with a 20 mill liner. A vac truck was called when spill was discovered. Oil was skimmed and put back into the holding tanks. Approximately 10 bbls were not recovered. Oil is still seeping through gravel in firewall. We will removed contaminated gravel and replace.

Final Remediation: All gravel was replaced and all fluids were picked up with a vacuum truck inside spill containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	James B. Campanella	Approved by Environmental Specialist:	
Title:	Member/Manager	Approval Date:	12/9/14
E-mail Address:	jbc@judahoil.com	Expiration Date:	NA
Date:	5/29/2013	Conditions of Approval:	Final
Phone:	575-746-1280	Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

JRP-1557