

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

DEC 08 2014

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address 2350 Marland Blvd Hobbs NM 88240	Telephone No. 432-631-6982
Facility Name WBDU # 42	Facility Type injection well

Surface Owner Millard Deck Estates	Mineral Owner BLM	API No. 30-025-20178
------------------------------------	-------------------	----------------------

LOCATION OF RELEASE

Unit Letter 1	Section 9	Township 21S	Range 37E	Feet from the 198'	North/South Line FSL	Feet from the 660'	East/West Line FEL	County Lea
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15 Barrels of water	Volume Recovered 5 Barrels of water
Source of Release injection line	Date and Hour of Occurrence 11/11/14	Date and Hour of Discovery 11/11/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeffery Robertson (BLM)	
By Whom? Bruce Baker	Date and Hour 11/12/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The release occurred due to a hole in 2 inch 90 degree fitting on the well head. The line was shut in and a vacuum truck was dispatched to pick up standing fluid.

Describe Area Affected and Cleanup Action Taken.* The majority of the release was contained to the pad with about 2,500 square feet of pasture affected on east side of well pad. The area was mapped and the wet area has been scraped and contaminated soil was hauled to a NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Approved by Environmental Specialist:	
Title: Environmental Technician	Approval Date: 12-8-14	Expiration Date: 2-8-14
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: <i>Site Supervisor signed</i> <i>Delinate & resident area open</i> <i>NMOCD guide - Submit Form C-141</i> <i>by 12-14.</i>	Attached <input type="checkbox"/> <i>IRP- 3435</i>
Date: 11/26/14	Phone: (432) 631-6982	<i>og 273</i> <i>2-10 1434 234516</i> <i>P70 1434 234688</i>

* Attach Additional Sheets If Necessary

DEC 11 2014