

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD** State of New Mexico  
Energy Minerals and Natural Resources  
**DEC 08 2014**  
Oil Conservation Division  
1220 South St. Francis Dr.  
**RECEIVED** Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Regency (Formerly Southern Union Gas)	Contact Crystal Callaway
Address 421 W. 3 <sup>rd</sup> Street, Suite 250, Ft. Worth, TX 76102	Telephone No. 817-302-9407
Facility Name R.R. Sims 10" MA-3	Facility Type 10" Natural Gas Gathering Line

Surface Owner: Sims Ranch	Mineral Owner	API No.
---------------------------	---------------	---------

#### LOCATION OF RELEASE

Unit Letter C	Section 3	Township 23S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.33946 Longitude -103.15354

#### NATURE OF RELEASE

Type of Release: Liquid/Natural Gas	Volume of Release: Unknown	Volume Recovered: None
Source of Release: 10" Line Leak	Date and Hour of Occurrence 9-23-2014	Date and Hour of Discovery 9-23-2014
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

A leak was discovered in the R. R. Sims 10" MA-3 line formerly operated by Southern Union Gas (Now Regency) on 9-23-2014. The line was repaired with a clamp. Upon review, it was discussed with the NMOCD and determined that filing of a Form C-141 was appropriate.

Describe Area Affected and Cleanup Action Taken.\*

On 11-19-2013, Apex Titan Personnel were onsite to oversee excavation of the leak site and collect confirmation samples.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature: *Crystal Callaway*

Printed Name: Crystal Callaway

Title: Sr. Env Remediation Spec

E-mail Address: *crystal.callaway@regency.com*

Date: 12/1/14 Phone: 817-307-6514

Approved by Environmental Specialist:

Approval Date: 12-9-14

Expiration Date: 2-9-15

Conditions of Approval:

*See Supplemental report.  
Revised & submitted on as per  
NMOCD guide. Submit final C-141  
by 2-9-15*

Attached ☐

IRP - 3436

\* Attach Additional Sheets If Necessary

**DEC 11 2014**

*09/14 21 219  
12/01/14 3424 2046  
12/19/14 3424 2239  
12/19/14 3424 1720*