

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Minerals and Natural Resources
Oil Conservation Division
RECEIVED 1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: DLJ Equipment Leasing, LTD	Contact Larry Gandy
Address P.O. Box 2140 Lovington, NM 88260	Telephone No. 575-396-0522
Facility Name: Sprinkle SWD	Facility Type SWD
Surface Owner NMSLO	Mineral Owner API No. 30-025-28521

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	4	19S	35E	1650	North	460	East	Lea

Latitude N 32 41.735 Longitude W 103 28.066 (2.5 miles west of the Intersection of 529 & 238 on south side of road)

NATURE OF RELEASE

Type of Release: Oil and Water	Volume of Release Estimated 1000-2000 bbl's	Volume Recovered 1680 bbl's
Source of Release: Produced Water Storage Tanks On-site	Date and Hour of Occurrence Nov 3, 2104 approx: 6-7pm	Date and Hour of Discovery Same- By-Passer called Police-On Fire
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bill Sonnamaker-OCD Telephone Call Sonnamaker-LGandy	
By Whom? Larry Gandy	Date and Hour Nov 04, 2014 9am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken. **Lightning struck tank battery, resulting fire completely destroyed tank battery facility. Fire compromised parts of the underlying secondary containment liner, but all released oil & water remained inside of berm area. Emergency Response actions were taken pursuant to state's rules and regulations. It appeared the oil released was consumed by the fire.**

Describe Area Affected and Cleanup Action Taken. **Emergency response actions consisted of fire fighting by local fire departments and water recovery by Gandy Corporation and hauled to GMI an approved OCD disposal. After site was released from Emergency Response Actions, Price LLC an Environmental Consultant collected surface and vertical samples under liner for submission of a remediation plan to OCD.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Wayne Price-Price LLC		
Title: Agent/Consultant for DLJ	Approval Date: 12-8-14	Expiration Date: 2-8-15
E-mail Address: wayneprice77@earthlink.net	Conditions of Approval: Site sample required before E Remediate per approved NMOCD guidelines	Attached <input type="checkbox"/> IRP- 3437
Date: November 26, 2014 Phone: 505-715-2809		

- Attach Additional Sheets If Necessary- Attached is a completed Phase I Environmental Site assessment; and a Phase II Remediation Plan for OCD Approval.

Submit full C-141 by 2-8-15

ogrid 261405

W7019 3424 8801

P7014 3424 9146

DEC 11 2014