HORRES OCD

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240

State of New Mexico

District II

811 S. First St., Artesia, NM 88210

Energy Minerals and Natural Resources DEC 6 9 2014

Revised August 8, 2011 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

District III 1000 Rio Brazos Road, Aztec, NM 87410

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 RECEIVED

Oil Conservation Division 1220 South St. Francis Dr.

Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

Name of Co				····		Contact: Robert McNeill					
Address: 600 West Illinois Avenue, Midland TX 79701						Telephone No. 432-230-0077					
Facility Nar	ne: Bebida	as State #4H			F	Facility Type: Battery					
Surface Owner: State Mineral Owner						: State API No. 30-025-40857					
LOCATION OF RELEASE											
Unit Letter P							I I		West Line East	County Lea	
Latitude32.298553890879 Longitude -103.569999791543											
NATURE OF RELEASE											
Type of Release:							Volume of Release: Volume Recovered:				
Oil and Produced Water							4 bbls Oil; 20 bbls PW 3 bbls Oil; 19 bbls PW				
Source of Release:						Date and Hour of Occurrence: Date and Hour of Discovery:					
Tank Overflow Was Immediate Notice Given?							11/27/2014 6:00 am				
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required							II 1 ES, 10 Whom?				
By Whom? Was a Watercourse Reached?							Date and Hour:				
was a water	course Read	l No		If YES, Volume Impacting the Watercourse.							
☐ Yes ⊠ No											
If a Watercourse was Impacted, Describe Fully.*											
Describe Cause of Problem and Remedial Action Taken.*											
This release was caused by a tank overflow due to a failure with a flow control valve. Repairs were made to the facility and vacuum trucks were dispatched											
to recover all standing fluid and dispose of at an NMOCD approved facility.											
Describe Area Affected and Cleanup Action Taken.*											
This release was contained inside the lined facility and was able to be cleaned and put back into service.											
I hereby certi	fy that the	nformation gi	ven above	is true and comple	ete to the	e best of my	knowledge and u	ndersta	nd that pursi	uant to NMOCD rules and	
										ases which may endanger	
										eve the operator of liability	
										surface water, human health	
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations. Signature:						OIL-GONSERVATION DIVISION					
						1 1 119					
				A	Approved by Environmental Specialist:						
Printed Name: Amanda Trujillo											
Title: Senior Environmental Coordinator						Approval Date: 12-9-19 Expiration D			Date: 2-9-15		
E-mail Address: atrujillo@concho.com Date: December 4, 2014 Phone: 575-748-6940						Conditions of Approval: Sate Supple signal. Patrice Mr rube our app Nroco guilos. Subiris full (-141 by			6' m	Attached	
									Leco	IRP 3442	
Date: December 4, 2014 Phone: 575-748-6940 Pho											
1-9-/C											
						- 10				n10143435 4362	

p70143435 4362