

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD
State of New Mexico
Energy Minerals and Natural Resources

DEC 11 2014
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Devon Energy	Contact Kenny Kidd
Address PO Box 250 Artesia, NM 88211	Telephone No. 575- 513-8545
Facility Name Morton Solid State Unit #4	Facility Type Oil

Surface Owner	Mineral Owner	API No. 30-025-35228
---------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter C	Section 4	Township 15S	Range 34E	Feet from the 660	North/South Line NORTH	Feet from the 1980	East/West Line WEST	County LEA
-------------------------	---------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude: __ Longitude: __

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 36bbls	Volume Recovered 20bbls
Source of Release Fiberglass tank struck by lightning	Date and Hour of Occurrence 5/24/14	Date and Hour of Discovery 5/24/14 8:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kenny Kidd-Foreman/ Ruben Garcia-Assistant Foreman/ Scott Poe-EHS/Jerry Mathews-Superintendent/Hobbs OCD-Voicemail/BLM-Voicemail	
By Whom? Jeff Ables	Date and Hour 5/24/14 8:45 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Fiberglass tank was struck by lightning causing 36 barrels of produced water to be released within the burm facility. A vacuum truck was immediately called to location and 20 bbls of produced water was recovered from the burmed area. The burm was breached with a flow path to the south of the burm. The facility was shut in for repairs.

Describe Area Affected and Cleanup Action Taken.*

The area affected was within the burm approximately 20 feet wide by 80 feet long and to the south of the burm. Talon LPE was contacted to perform the site assessment and soil sampling activities.

Action Taken

Talon/LPE completed the remediation activities per NMOCD approved work plan. The impacted area inside the berm was excavated to a depth of 4.5 feet deep. The impacted area outside the fence was excavated to a depth of 1.5 foot deep. All the contaminated soil was transported to Lea Land, an approved disposal facility. The excavated area inside the berm was backfilled with new/clean caliche from Lea Land and new top soil was used outside the fence. The areas were re-contoured to match the surrounding location. The small area of the pasture was seeded. No further actions are required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 12-11-14	Expiration Date: _____
E-mail Address: corina.moya@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 4, 2014	Phone: 575-746-5559	18A-3050

DEC 12 2014 P7019147 511 96