

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **HOBBS OCD**
Energy Minerals and Natural Resources
Oil Conservation Division **DEC 04 2014**
1220 South St. Francis Dr.
Santa Fe, NM 87505 **RECEIVED**

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Burgundy Oil and Gas of New Mexico	Contact: Ben Taylor
Address: 401 W Texas Suite 1003 Midland, TX 79701	Telephone No. 432-684-4033
Facility Name: State Vacuum Unit #15	Facility Type: WIW

Surface Owner State	Mineral Owner State	API No. 30-025-02173
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter 1	Section 32	Township 17S	Range 34E	Feet from the 1980	North/South Line South	Feet from 680	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------	------------------------	---------------

Latitude: 32.7895034299485 Longitude -103.576372754491

NATURE OF RELEASE



Type of Release: Produced water	Volume of Release 3bbls	Volume Recovered 0bbls
Source of Release: Flowline	Date and Hour of Occurrence 08-28-14 14:00	Date and Hour of Discovery 08-28-14 14:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD M Whitaker	
By Whom? Ben Taylor	Date and Hour: 08/28/14 14:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
A rupture occurred in an injection line next to the well. DFSI was retained to remediate the site.

Describe Area Affected and Cleanup Action Taken.
This site has been fully remediated to the NMOCD Guidelines for Releases and Spills. A Closure report has been submitted with this attached Final C-141

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ben Taylor	Approved by Environmental Specialist: 	
Title: Field Foreman	Approval Date: 12-11-14	Expiration Date: _____
E-mail Address: btaylor.bogi@att.net	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date 11/20/2014 Phone: 432-557-2684		1 RP-3300

* Attach Additional Sheets If Necessary

DEC 12 2014

2701424626337
2701424626537