Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505														
Release Notification and Corrective Action														
						OPERA	ΓOR		Initia	l Report	\boxtimes	Final Report		
Name of Company Devon Energy							Contact Kenny Kidd							
Address PO Box 250 Artesia, NM 88211							Telephone No. 575- 513-8545							
Facility Name Rio Blanco 4 Fed 3 SWD1							Facility Type SWD							
Surface Ow	ner		wner	API No. 30-025-3					6425					
LOCATION OF RELEASE														
					North/	South Line Feet from the Eas OUTH 1650			t/West Line County EAST LEA					
Latitude: Longitude:														
NATURE OF RELEASE														
Type of Release Produced Water											Recovered 65bbls			
Source of Release Charge pump pipe							Date and Hour of OccurrenceDate and I5/30/145/30/14 1			Hour of Discovery				
Was Immediate Notice Given?							Whom?	1						
Yes 🗌 No 🗍 Not Required						Kenny Kidd-Foreman/ Garry Michael-Assistant Foreman/ Scott Poe- EHS/Jerry Mathews-Superintendent/Hobbs OCD-Geoffery Leking/BLM- Jeff Robertson								
By Whom? Matt Nettles							Date and Hour 5/30/14 11:30 AM							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.								
\Box Yes \boxtimes No														
If a Watercourse was Impacted, Describe Fully.*														
Describe Cau	se of Probl	em and Reme	dial Actio	n Taken.*										
The needle valve came out of the pipe which is connected to the charge pump. This caused 65 barrels of produced water to be released. 60 barrels in the containment and 5 bbls outside of the containment. The well was shut off. A vacuum truck was immediately called for vacuum services. 65 barrels of produced water was recovered. The pump was repaired.														
Describe Area Affected and Cleanup Action Taken.* The area affected was within the burm approximately 30 feet wide by 60 feet long. The affected area outside the containment was approximately 5 feet wide by 75 feet long. Talon LPE was contacted to perform the site assessment and soil sampling activities.														
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.														
Signature: Corina Moya						OIL CONSERVATION DIVISION								
Printed Name	e: Corina N	Ioya			Approved by Environmental Specialist:									
Title: Field Admin Support						Approval Da	pproval Date: 12-11-19 Expiration Date:							
E-mail Address: corina.moya@dvn.com						Conditions of Approval:			Attached					
Date: Decem	her 3 2014		/5-748-0174		~			IR P- 3450						

* Attach Additional Sheets If Necessary

DEC 1 2 2014 MT0193454 4342 PT0143454 4663

6137