

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBSOCD

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Regency Field Service LLC	Contact	Phillip Little
Address	1226 Sal NM 88252	Telephone No.	575-631-2576
Facility Name	TRUNK M 2	Facility Type	Gas Gathering
Surface Owner	Crawford	Mineral Owner	
		API No.	30-025-27276

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	19	23S	31E					

Latitude 33.222° N Longitude 103.203° W

### NATURE OF RELEASE

Type of Release	Crude Oil, Nat Gas, and Produced Water	Volume of Release	6 bbls	Volume Recovered	0 bbls
Source of Release	20" Nat Gas Gathering Line	Date and Hour of Occurrence	1	Date and Hour of Discovery	12-5-14
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	UNKNOWN		1:00 p.m.
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Failure of a segment of 20" pipeline resulted in the release of approximately 6 bbls of fluid. Following the discovery pipeline was fitted with a clamp.

Describe Area Affected and Cleanup Action Taken.\*

The release affected approximately a 8' x 18' area. Panther Energy will remediate in accordance with NMOCD Regulatory Guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Phillip Little		
Title:	Approval Date: 12-7-14	Expiration Date: 2-7-15	
E-mail Address:	Conditions of Approval:		Attached <input type="checkbox"/>
Date:	525 S. Apple Road, Del Rio, NM 87830 E-mail: <a href="mailto:phillip@pantherenergy.com">phillip@pantherenergy.com</a> gordon. Subir. Rm (741) 342-1575		LRP-3756

\* Attach Additional Sheets If Necessary

21217

77017 341 2 94 38  
P701434928639

DEC 15 2014