

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 10 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name ConocoPhillips	API Number 3002500610
Property Name MCA	Well No. 67

Surface Location

L/L - Lot L	Section 21	Township 17S	Range 32E	Feet from 1980	N/S Line FSL	Feet From 660	E/W Line FWL	County Lea
-----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☒ GAS ☐	DATE 12/11/14
--	--	--	--	-------------------------

OBSERVED DATA

	(A) Surface	(B) Interim 1	(C) Interim 2	(D) Prod Casing	(E) Tubing
Pressure		N/A	N/A	0 PSI	0 PSI
Flow Characteristics					
Puff	☒ N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	☒ N	Y / N	Y / N	☒ N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Inferred for
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Water/Gas if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

This well has just been repaired due to a
Packer Leak

FOR RECORD ONLY

BS 12/12/2014

Signature: Chris Silva	OIL CONSERVATION DIVISION
Printed name: CHRIS SILVA	Entered into RBDMS
Title: MSD	Re-test
E-mail Address: CHRISTIAN.SILVA@CONOCOPHILLIPS.COM	
Date: 12-11-14	Phone: 505-704-2252
Witness:	

DEC 16 2014