

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD

DEC 18 2014

RECEIVED

State of New Mexico

Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company EOG Resources, Inc.	Contact Zane Kurtz
Address 5509 Champions Drive, Midland, TX 79706	Telephone No. 432-425-2023
Facility Name Fox 30 State #3 and #4	Facility Type lease road near active well

Surface Owner Mark McCloy	Mineral Owner	API No. 30-025-41249 (#3)
---------------------------	---------------	---------------------------

LOCATION OF RELEASE

Unit Letter H	Section 30	Township 25S	Range 34E	Feet from the 2140'	North/South Line N	Feet from the 715'	East/West Line E	County Lea
------------------	---------------	-----------------	--------------	------------------------	-----------------------	-----------------------	---------------------	---------------

Latitude 32.1029 Longitude -103.5027

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50 bbls	Volume Recovered 40 bbls
Source of Release Produced Water Poly Line	Date and Hour of Occurrence 11-21-2014	Date and Hour of Discovery 1500
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*

Lease op found leaking 4 inch poly line on lease road near well. About 50 bbls of produced water was spilled and 40 bbls was recovered by vacuum truck. Impacted area was excavated with backhoe and CH2M HILL was onsite to collect soil samples to delineate vertical and horizontal impacts. Soil is stockpiled on poly plastic and will be hauled off for proper disposal and clean soil will be used to backfill excavated area.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Zane Kurtz

Title: Sr. Environmental Rep.

E-mail Address: zane_kurtz@eogresources.com

Date: 12-16-2014 Phone: 432-425-2023

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date: 12-16-14

Expiration Date: 2-16-15

Conditions of Approval:

Site specific report. Replete
and include area as per NMOCD

Attached ☐

IRP. 3460

Final. Submit final C-141 by
2-16-15

* Attach Additional Sheets If Necessary

DEC 18 2014

7372
N701435029870

P701435030001