

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

Oil Conservation Division

1220 S. St. Francis Dr.

Santa Fe, NM 87505

Form C-141

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: GC Federal Battery	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-35814
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	19	17S	32E	2225	South	2406	East	Lea

Latitude N 32°48.739 Longitude W104°06.993'

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: Oil 15 bbls	Volume Recovered: Oil 15 bbls
Source of Release: Fire tube on Heater Treater	Date and Hour of Occurrence: 12/7/2014 7:00 pm	Date and Hour of Discovery: 12/7/2014 7:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Dr. Tomas Oberding - OCD	
By Whom? Lupe Carrasco	Date and Hour: 12/9/2014 4:28 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a hole that developed on the fire tube of the heater treater causing a fire and the release of fluid which were contained within the bermed area. Emergency crews were dispatched to suppress the fire and a vacuum truck was dispatched to recover standing fluids.

Describe Area Affected and Cleanup Action Taken.*

The release was contained within the battery. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lupe Carrasco	Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 12-12-14	Expiration Date: -
E-mail Address: gcarrasco@concho.com	Conditions of Approval: -	Attached <input type="checkbox"/>
Date: December 17, 2014 Phone: 575-748-6940	1RA 3962	

* Attach Additional Sheets If Necessary

229132

770 14351434 38

P701435143587

DEC 18 2014