<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Santa Fe, NW 87303													
fAB1435839131 Release Notification and Corrective Action													
n-AB16	13583		OPERATOR			☐ Initial Report ⊠ Final Report							
Name of Co	ompany Er	Contact Dina Babinski											
Address PC	Box 4324	Telephone No. 210-528-3824											
Facility Nat Lateral	ne Pipelin		Facility Type Gas Gathering Pipeline										
Surface Ow	ner Privat	wner I	NA - Pipeline			API No. NA							
LOCATION OF RELEASE													
					North	h/South Line Feet from the 120		East/West Line West		County Eddy			
Latitude <u>N 32.1801</u> Longitude <u>W -104.0513</u>													
NATURE OF RELEASE													
Type of Release Natural Gas							Volume of Release 4,290 MCF			Volume Recovered NA			
Source of Release Pipeline Blowdown, Overpressure							Date and Hour of Occurrence 12/11/2014 @ 7:40 MST			Date and Hour of Discovery 12/11/2014 @ 15:00 MST			
Was Immediate Notice Given?							If YES, To Whom?						
☐ Yes ☐ No ☐ Not Required							d Mike Bratcher, NMOCD						
By Whom? Osman De Leon						Date and Hour 12/11/2014 @ 15:30 MST							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*							NM OIL CONSERVATION						
If a Watercou	irse was Im	. ANTESIA DISTRICT											
DEC 2 3 2014													
Describe Cause of Problem and Remedial Action Taken.*							RECEIVED						
Due to down	stroom flo	w restrictions	ninalina	pressure above	tha mas	zimum allow	ahla anaratina n	raccura	raquirad n	inalina blo	wdown	to relieve	
Due to downstream flow restrictions, pipeline pressure above the maximum allowable operating pressure required pipeline blowdown to relieve pressure in an effort to prevent potential pipeline failure and additional gas releases.													
Describe Area Affected and Cleanup Action Taken.*													
The pipeline blowdown was performed to relieve pressure from the system. No liquid spills occurred requiring any cleanup actions.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
OIL CONSERVAT										DIVISIO	)N		
Signature: AM Fulls													
							Approved by						
Printed Name	: Jon E. F	ields				The The							
Title: Direct	tor, Field E	nvi <b>r</b> onmental		Approval Date: 2/23/14 Expiration Date: NA									
E-mail Address: jefields@eprod.com						Conditions of Approval:							
Date:	Q-18	2014	Phone:	713-381-6684		+ new							

Date: 2-18. 2014 I \* Attach Additional Sheets If Necessary



## ENTERPRISE PRODUCTS PARTNERS L.P. ENTERPRISE PRODUCTS HOLDINGS LLC (General Partner)

**ENTERPRISE PRODUCTS OPERATING LLC** 

NM OIL CONSERVATION

ARTESIA DISTRICT
DEC 2 3 2014

December 18, 2014

RECEIVED

7014 2120 0001 5336 8360 Return Receipt Requested

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE: Form C-141 Report for Enterprise Field Services LLC Releases on Carlsbad Area Gathering Lines

Dear Mr. Bratcher:

Enclosed, please find the required C-141 Form for the unplanned blowdown on our East Trunk A Line in Eddy County on December 11, 2014. The pipeline was blown down to relieve pressure from the system and prevent damage to the pipeline and potential gas leaks. This report is sent to follow-up on the immediate verbal notification by Osman De Leon on December 11, 2014 at 15:30 MST and NMAC 19.15.29 requirements.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor by phone at 210-528-3824 or via email at <a href="mailto:djbabinski@eprod.com">djbabinski@eprod.com</a> or me directly at 713-318-6684.

Yours truly,

Jon E. Fields

Director, Field Environmental

Ion E. Fields

/sjn enclosure