

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBSOCD

DEC 22 2014

RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company- Harvey E. Yates Company	Contact- Tammy R. Link	
Address - P.O. Box 1933, Roswell, NM 88201-1933	Telephone No. 575-623-6601	
Facility Name - Richardson Fee #1	Facility Type - API #30-025-27610	
Surface Owner - Fee	Mineral Owner	API No. 30-025-27610

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	5	14S	36E	660'	N	1980'	W	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release - (ILLEGAL DUMPING) of Produced Water	Volume of Release - 100 bbls	Volume Recovered - 0-
Source of Release	Date and Hour of Occurrence 12/17/14 after 5:00 pm	Date and Hour of Discovery-12/18/14 5:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bill with OCD in Hobbs	
By Whom?	Date and Hour 12/19/14 at 11:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Illegal dumping of produced water.		
Describe Area Affected and Cleanup Action Taken.* Backhoe called to scrape top layer and haul off contaminated soil, will be collecting soil samples.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tammy R. Link	Approved by Environmental Specialist:	
Title: Engineering Tech	Approval Date: 1-5-2015	Expiration Date: 3-5-2015
E-mail Address: tlink@heycoenergy.com	Conditions of Approval: <i>Site Super repair Revised conditions on map NMOCD grants Submittal</i>	Attached <input type="checkbox"/> IRP-3470
Date: 12/19/2014 Phone: 575-623-6601	C-141 by 3-5-2015	

* Attach Additional Sheets If Necessary

258462
N70 150535 870
P70 1500536043

JAN 08 2015